

Why was there a wall near runway at S Korea plane crash airport? Free 311224

Description



Why was there a wall near runway at S Korea plane crash airport?

Why was there a wall near runway at S Korea plane crash airport?

Aviation experts have raised questions about an "unusual" concrete wall near the runway and its role in the South Korea plane crash that killed 179 people.

Footage shows the Jeju Air plane coming off the runway before colliding with the wall and bursting into flames at Muan International Airport.

Authorities investigating the cause of South Korea's worst-ever plane crash are considering the significance of the concrete wall's location about 250m (820ft) off the end of the runway.

Air safety expert David Learmount said that if the "obstruction" was not there, the plane "would have come to rest with most – possibly all – those on board still alive".

The pilot reported that the plane had struck a bird and then aborted the original landing and requested permission to land from the opposite direction.

The plane came down some distance along the 2,800m runway and appeared to land without using its wheels or any other landing gear.

Mr Learmount said the landing was "as good as a flapless/gearless touchdown could be: wings level, nose not too high to avoid breaking the tail" and the plane had not sustained substantial damage as it slid along the runway.

"The reason so many people died was not the landing as such, but the fact that the aircraft collided with a very hard obstruction just beyond the runway end," he said.

Christian Beckert, a Lufthansa pilot based in Munich, called the concrete structure "unusual", telling Reuters news agency: "Normally, on an airport with a runway at the end, you don't have a wall."

The concrete structure holds a navigation system that assists aircraft landings – known as a localiser – according to South Korea's Yonhap News Agency.

At 4m high, it is covered with dirt and was raised to keep the localiser level with the runway to ensure it functions properly, Yonhap reported.

South Korea's transport ministry has said that other airports in the country and some overseas have the equipment installed with concrete structures. However officials will examine whether it should have been made with lighter materials that would break more easily upon impact.

Chris Kingswood, a pilot with 48 years' experience who has flown the same type of aircraft involved in the crash, told BBC News: "Obstacles within a certain range and distance of the runway are required to be frangible, which means that if an aircraft strikes them that they do break.

"It does seem unusual that it's such a rigid thing. The aircraft, from what I understand, was travelling very fast, landed a long way down the runway, so it will have gone a long way past the end of the

runway... so where will you draw the line with that? That's certainly something that will be investigated.

"Aeroplanes are not strong structures – they are, by design, light to make them efficient in flight. They're not really designed to go high-speed on its belly so any kind of structure could cause the fuselage to break up and then be catastrophic.

"The fuel is kept in the wings so once the wing ruptures, then the potential for fire is significant.

"So it's not a given that if the wall had not been there, it would have been a completely different outcome."

Mr Kingswood said he would be "surprised if the airfield hadn't met all the requirements in accordance with industry standards".

"I suspect if we went around the airfields at a lot of major international airports... we would find a lot of obstacles that could similarly be accused of presenting a hazard," he added.

Aviation analyst Sally Gethin questioned whether the pilot knew the barrier was there, particularly given the plane was approaching from the opposite direction from the usual landing approach.

She told BBC News: "We need to know, were (the pilots) aware there was this hard boundary at the end?

"If they were directed by the control tower to reverse the use of the runway the second time around, that should come out in the investigation of the black boxes.

"I think there are so many questions."

Want to earn £20 an hour call 020 8269 4500 24 Hour Line Option 2

Sureserve Compliance South (Formerly K&T Heating)

TEXT

Hotel Booking <u>Home Page Banzai Japan</u> https://www.youtube.com/watch?v=zQKpQJhRzRY&list=PLtnxlcx-lhllKCgG4pZ4qpFN1A9WrdIxZ

Category

1. News

Date Created 31/12/2024 Author

admin